

2010 BMW 5 series L6, 3.0L

WBANV1C58AC443157

Odometer: 115,839 miles

1 Confirmed Code

P0015 "B" Camshaft Position - Timing Over-Retarded Bank 1

3 Pending Codes

P0015 "B" Camshaft Position - Timing Over-Retarded Bank 1

P0305 Cylinder 5 Misfire Detected

P0306 Cylinder 6 Misfire Detected

1 Permanent Code

P0015 "B" Camshaft Position - Timing Over-Retarded Bank 1

0 Body Gateway Module Codes

4 Engine Codes

2A87 outlet-Vanos variable cam control test, mechanics
HISTORY

29D1 No description available
HISTORY

29D2 No description available
HISTORY

29CC misfirings, several cylinders
HISTORY

1 Gearbox Controller Code

507D Parking lock put out, defective
HISTORY

1 Dynamic Stability Control Code

6E83 - PT-CAN: Signal ST IND FLTR in message STAT RDC (ID 0x31C) invalid (Sender RDC) diesen FC bitte ausblenden (Bosch SW-Fehler)
HISTORY

0 Interior Protection Codes

0 Instrument Cluster Codes

0 Light Module Codes

0 Central Information Display Codes

0 Air Conditioning Codes

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.